



## JIS GAS MALE 60° CONE



PART NO.	THREAD		DIMENSIONS					
	E	F			A	B	L	S1
	G1/8"X28	G1/8"X28			12	12	30	14
	G1/4"X19	G1/4"X19			16	16	38	17
	G3/8"X19	G3/8"X19			18	18	42	19
	G1/2"X14	G1/2"X14			20	20	48	22
	G3/4"X14	G3/4"X14			22	22	54	30
	G1"X11	G1"X11			24	24	59	36
	G1.1/4"X11	G1.1/4"X11			27	27	67	46
	G1.1/2"X11	G1.1/2"X11			27	27	69	50
	G2"X11	G2"X11			30	30	77	65

## JIS GAS MALE 60° CONE / BSPT MALE



PART NO.	THREAD		DIMENSIONS					
	E	F			A	B	L	S1
	G1/8"X28	R1/8"X28			12	10	28	14
	G1/8"X28	R1/4"X19			12	14.5	32.5	17
	G1/4"X19	R1/4"X19			16	14.5	36.5	17
	G1/4"X19	R1/8"X28			16	10	32	17
	G1/4"X19	R3/8"X19			16	15	37	19
	G1/4"X19	R1/2"X14			16	20	44	22
	G3/8"X19	R3/8"X19			18	15	39	19
	G3/8"X19	R1/4"X19			18	14.5	40.5	22
	G3/8"X19	R1/2"X14			18	20	46	22
	G1/2"X14	R1/2"X14			20	20	48	22
	G1/2"X14	R1/4"X19			20	14.5	42.5	22
	G1/2"X14	R3/8"X19			20	15	45	27
	G1/2"X14	R3/4"X14			20	20	50	27
	G3/4"X14	R3/4"X14			22	20	53	30
	G3/4"X14	R1/2"X14			22	20	52	30
	G3/4"X14	R1"X11			22	25.5	58.5	36
	G1"X11	R1"X11			24	25.5	62.5	41
	G1"X11	R3/4"X14			24	20	57	41
	G1.1/4"X11	R1.1/4"X11			27	26.5	66	46
	G1.1/2"X11	R1.1/2"X11			27	26.5	67.5	50
	G2"X11	R2"X11			30	30	77	65